

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Block loaded with AMP, in a 0.2 M HNO₃ and 2 mg/L cesium

Figure 1




Block loaded with AMP, in a 2 M HNO_3 and 1000 mg/L cesium

Figure 2




Block loaded with AMP, in a 1.5 M HNO_3 and 500 mg/L cesium

Figure 3



Cs-137 Breakthrough vs. Time
Block Loaded with AMP, Feed at 4 BV/hr, 1.5 M HNO₃ and 1 mg/L Cs.


Figure 4



Cs-137 Breakthrough vs. Time
Blocks loaded with AMP, Feed at 2 BV/hr, 1.5 M HNO₃ and 1mg/L Cs.


Figure 5

Conc. Of Cs-137 in effluent/conc. Of Cs-137 in original feed solution




Cs-137 Fractional Breakthrough
Blocks loaded with AMP, Feed at 2 BV/hr., 1.5 M HNO₃ and 1 mg/L Cs.

Figure 6




Block Loaded with CMPO, in 2.5 M HNO₃ and 74 Bq/mL Am-241

Figure 7




Block Loaded with CMPO, in 2.5 M HNO₃ and 70 Bq/mL Am-241

Figure 8




Acidic tank waste spiked with ^{137}Cs .
Blocks loaded with AMP.

Figure 9



Volume of tank waste treated (A)
Bed Material Blocks loaded with AMP (B)
HUPed bed material (C)

Figure 10



Bed Volumes Processed. Blocks loaded with CMPO.

Figure 11